



## Service Letter No. EX1 August, 1993

**Subject: Model EX360H/EX466A Installation Manual**

The reference to the gasket, P/N 019407, in the IMPORTANT! statement at the bottom of page 3 is erroneous. Two (2) gaskets, P/N 018892, are required for the installation of the Model EX360H and EX466A. The gasket, P/N 019407, is not required in the installation of the models EX360H and EX466A.

The statement should read as follows:

### **IMPORTANT!**

Make sure that the gaskets, P/N 018892, are installed both between the turbo output and the exhaust pipe **and also** between the exhaust pipe and the Extarder inlet. Failure to correctly install these gaskets will result in a loss of retarding performance.

The initial shipment of the Model EX360H aftermarket kits, P/N 019091, along with the informational packet mailed on August 19, 1993, contain manuals with this error. Please correct any manuals found to contain this error. Corrected manuals will have the P/N 019762B.

**SERVICE LETTER**