



Service Letter No. EX6 January, 1995

Subject: Extarder™ Parts Manual, P/N 020194

Models Affected: EX408, EX466H and EX530

Please note the following errors in the recently published Parts Manual, P/N 020194, for Extarder Models EX408, EX466H and EX530.

On page 3 under the heading, "Control Group", Ill. No. 2 is listed as P/N 020020 Switch Bracket. The correct part number is P/N 020202 Switch Bracket.

On page 3 under the heading, "Assembly Groups", each subheading lists Exhaust Sleeve quantities as one (1). The correct quantity per kit for each listing is two (2) Exhaust Sleeves.

On page 5 under the heading, "Wire Harness (NI), P/N 018899": This is an optional item not included in the group and must be ordered separately.

We recommend making these changes to your manual at your earliest convenience.

SERVICE LETTER