



# *Service Letter*

---

**Service Letter No. 398**  
**July, 1994**

**SUBJECT: New Trigger Cap**

**MODELS AFFECTED: 349A**

In March 1994, Jacobs improved the Model 349A Trigger Cap, P/N 016709, by improving the thread form. These caps were installed on brakes starting with housing serial number J015067. The thread form of the trigger bore in the housing had been improved earlier (August 1993), starting with brake housing serial number J010098. The combination of these two improvements has resulted in increased durability.

Be sure to refer to the Model 349A Installation Manual (P/N 018312) or Maintenance Manual (P/N 018151) for proper installation of the trigger assembly. The trigger cap should be tightened to **no more than 35 lbft. of torque.**

This is a Jacobs product improvement and not subject to campaign.