



Service Letter

**Service Letter No. 404
September, 1994**

SUBJECT: Mounting Stud Washers

MODELS AFFECTED: 346D

Starting in January 1994, Jacobs eliminated the P/N 013695 Stud Washer on the Model 346D engine retarder and replaced it with the P/N 016497 Stud Washer previously used only on the Model 349/349A retarders. This was done simply to standardize on one part in two very similar applications.

This change effects the Model 346 Series Tune-up Kit (P/N 014087) as well as service parts. Any inventory of P/N 013695 washers is to be used.

This is a product improvement and not subject to campaign.