




Service Letter No. EX7 October, 1995

Subject: Changes to 110 mm Extarder™ Models

Models Affected: EXC83 and EX3116

Two changes have been made to all 110 mm brake housings for the Jacobs Extarder. The housing length has reduced from 92 mm to 82.5 mm. Also, the second ear has been removed from the housing assembly. These changes do not affect operation or performance in any way. They are strictly a design change due to manufacturing process upgrades. The size of the butterfly has not changed.

There is no change in availability or price.



SERVICE LETTER