# **Guidanz<sup>®</sup> Diagnostic Toolkit**

### Mobile Based – Immediate Assessment

 After logging into Guidanz Mobile, on the menu screen, click "New Assessment".





- Guidanz Mobile will automatically connect to the selected device.
- Inline 7 and Inline Mini are the 2 devices that can be used with Guidanz Mobile. These devices can connect via Bluetooth.

### **Guidanz<sup>®</sup> Diagnostic Toolkit**

#### Mobile Based – Immediate Assessment



# **Guidanz® Diagnostic Toolkit**

### Mobile Based – Immediate Assessment

				Cummins Guidanz
	If any Calibration updates are available for the ECM, a screen will appear with the information.		Press th	Lalibration Update Available Calibration Update Available for installation. Rew ECM Code EF10708.12 is available for installation. Begin Process button to learn more about the new calibration, download the file to this phone, and install it to the engine. Begin Process Install Later
8:46AM Thu Q 1XKAD49 Taul	ect 19			
PRIMARY 451	vice within 3 days FAULTS Injector Metering Rail 1 Pressure Sensor Circuit Voltage Above Normal or Shorted to High Source 1 Count Active		•	A message may appear indicating when service is needed.
	Typical service time for fault: 91% 0.2 2.4 4.6 0% hours hours hours 0%		•	Each Fault Code will be listed with estimates on service times.
<u>272</u>	Engine Fuel Pump Pressurizing Assembly 1 Circuit         Voltage Above Normal or Shorted to High Source         1       Count         Active         Typical service time for fault:         50%	>	•	Clicking the Fault Code will open the Overview for more information.
2274	02       24       46       Over 6         hours       hours       hours       hours         Exhaust Gas Recirculation Differential Pressure Sensor Circuit         Voltage Below Normal or Shorted to Low Source       2         1       Count       Active         No estimated repair data available for this fault.       2         Select Accessibility Code.       2	_ >	•	Clicking the arrow will open information about potential parts for the repair.
Ē	< ₹ ₩			Cummins 3

# **Guidanz<sup>®</sup> Diagnostic Toolkit**



- If available, a list of parts with the probability of needing replacement will appear.
- Open the Job Drawer to get more options.

3:48 AM Thu Oct 19				হ 100% 🛄	
		Cummins Guida	anz		
1XKAD49XXGJ	499205 〉Engir	ne #1			
🛣 Fault Det	ails				
	<	₽			
Event Folder					
🕂 Create Serv	ice Request		$\rightarrow$		
🕂 Create new	ECM Image			>	
🕂 Make New I	mmediate Assess	ment		>	
Complete Se	ervice Event			>	
• View Event	Folder Details			$\rightarrow$	
Event Folder			WO-20	0231019-084355	
Immediate Asse	essment	IAS-101923002600			
VIN			1XKAD	49XXGJ499205	
ESN			79838572		
Service Model			ISX	15 CM2350 X101	
Date			Oct 19, 2023 at 0	8:44:06 AM EDT	
Customer Name	e			Ralph Kendall	
Customer Unit I	Number			22554	
Odometer/Engi	ne Hours			0.0 mi	
Field A Tap to v	<b>ctions</b> iew field action	s		>	

Close Drawe

			÷ 1007
		Cummins Guidanz	
1XKAD4	9XXGJ499205 〉Eng	jine #1	
🛣 Fau	lt Details		
<u>272</u>	<b>Engine Fuel Pump P</b> Voltage Above Norm	ressurizing Assembly 1 Circ al or Shorted to High Source	uit
SERVICE	ESTIMATES		/
Fuel Pu	mp Actuator		72% probabili
Electric	al Connector		11% probabili
OEM C	omponent		5% probabili
Engine	Wiring Harness		3% probabili
	0% 0%		
0-2 hours Service ti procedure	0% 0%     0	e and are not intended to rep	place proper troubleshoot
0-2 hours F Service ti procedury FAULT IN	0%     0%       0%     0%       0urs     0%       nours     0       mes are only an estimate       es.Learn more	e and are not intended to rep	place proper troubleshoot
O-2 hours Service ti procedury FAULT IN	0% 0%     0% 0%     0ver 6     hours  mes are only an estimate es.Learn more  FORMATION  Count	e and are not intended to rep	olace proper troubleshoot
0-2 hours Service ti procedur FAULT IN	OM     OM	e and are not intended to rep	place proper troubleshoot
0 - 2 hours Service ti procedur FAULT IN 1 1347	Cours     O%     O	e and are not intended to rep	blace proper troubleshoot
Service ti procedur FAULT IN 1 1347 3	Cours     Cours     Cours     Cours     Cours     Cours     Cours     Cours     Cours     Count     Count     Count     Count     FORMATION     Count     Count     FON     FMI	e and are not intended to rep	olace proper troubleshoot
Service ti procedur FAULT IN 1347 3 2076:51	O% 0%     O% 0%     Over 6     ours     ours     only an estimate es.Learn more  FORMATION  Count  Active  SPN  FMI  #47 ECt fime (Key On Tim	e and are not intended to rep	blace proper troubleshoot
0 - 2 Nours Service ti procedure FAULT IN 1 1347 3 2076:51 0000003	orgen constraints     orgen constraints	e and are not intended to rep e) (h:m:s)	olace proper troubleshoot

 To send the information to Guidanz®, click the Create Service Request option.