



Jacobs Vehicle Systems®

Parts & Service Update

**No. 2020-02
January, 2020**

MX11 Engine Brake Service Parts

Jacobs Model Affected: 108

There is no tune-up kit available for the MX11 as it includes non-serviceable rocker arms. See spec sheet for part numbers for available serviceable parts.